

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00012	Policy	POL-72840188
Vehicle	2024 Audi Q5	VIN	JTP1XEHZLAVZFU3B8
Location	Seremban	Date	2026-05-26
Weather	Rain	Road	Wet Asphalt

Coverage Assessment

The insured reported a front-left impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Tail lamp, Left headlamp, Front bumper, Hood. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 8 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 26 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 9,600.

Damage Area	Severity	Recommendation
Right door	Moderate	Repair
Left fender	Major	Replace
Rear bumper	Major	Repair
Hood	Moderate	Replace

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.