

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00014	Policy	POL-37042091
Vehicle	2025 Mazda CX-5	VIN	JTZVBZUDF1B0E07R1
Location	Penang	Date	2026-05-15
Weather	Cloudy	Road	Urban Road

Coverage Assessment

The insured reported a front-left impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Front bumper, Tail lamp, Left headlamp, Hood. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 3 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 17 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 23,500.

Damage Area	Severity	Recommendation
Rear bumper	Moderate	Repair
Front bumper	Major	Replace
Hood	Moderate	Replace
Left fender	Moderate	Repair

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.