

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00015	Policy	POL-65151950
Vehicle	2021 Mercedes-Benz GLC	VIN	JT86PX0B90YD07UN4
Location	Johor Bahru	Date	2026-05-25
Weather	Overcast	Road	Urban Road

Coverage Assessment

The insured reported a front-left impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Left headlamp, Hood, Front bumper, Left fender. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 5 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 17 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 20,499.

Damage Area	Severity	Recommendation
Left headlamp	Minor	Inspect
Hood	Minor	Repair
Tail lamp	Minor	Repair
Left fender	Major	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.