

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00016	Policy	POL-91093178
Vehicle	2024 Hyundai Tucson	VIN	JTB3HT40BG1B0XHJP
Location	Shah Alam	Date	2026-05-24
Weather	Rain	Road	Urban Road

Coverage Assessment

The insured reported a flood exposure involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Left fender, Rear bumper, Right door, Left headlamp. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 7 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 13 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 10,980.

Damage Area	Severity	Recommendation
Front bumper	Major	Repair
Right door	Moderate	Repair
Left fender	Minor	Inspect
Hood	Moderate	Replace

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.