

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00017	Policy	POL-12215121
Vehicle	2023 Ford Ranger	VIN	JTT7GFPCD9T8XEXG8
Location	Penang	Date	2026-05-19
Weather	Rain	Road	Concrete

Coverage Assessment

The insured reported a right-side impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Left fender, Front bumper, Hood, Tail lamp. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 4 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 20 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 4,855.

Damage Area	Severity	Recommendation
Front bumper	Minor	Repair
Right door	Major	Replace
Tail lamp	Minor	Replace
Hood	Major	Replace

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.