

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00018	Policy	POL-25591379
Vehicle	2023 BMW 320i	VIN	JT55SBRC0C4W3VJCW
Location	Johor Bahru	Date	2026-05-20
Weather	Overcast	Road	Dry Asphalt

Coverage Assessment

The insured reported a multiple panel damage involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Hood, Right door, Front bumper, Rear bumper. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 4 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 21 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 11,534.

Damage Area	Severity	Recommendation
Right door	Major	Repair
Tail lamp	Moderate	Repair
Front bumper	Minor	Inspect
Hood	Minor	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.