

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00019	Policy	POL-97553630
Vehicle	2023 Hyundai Tucson	VIN	JT7K4P6U9ZPWH1AHP
Location	Johor Bahru	Date	2026-05-03
Weather	Cloudy	Road	Concrete

Coverage Assessment

The insured reported a rear-end collision involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Front bumper, Left fender, Hood, Tail lamp. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 6 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 18 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 7,118.

Damage Area	Severity	Recommendation
Rear bumper	Major	Repair
Hood	Major	Replace
Left headlamp	Minor	Replace
Front bumper	Moderate	Replace

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.