

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00021	Policy	POL-77382916
Vehicle	2020 Hyundai Tucson	VIN	JTWH5G3VTAD51X0VV
Location	Penang	Date	2026-05-14
Weather	Rain	Road	Concrete

Coverage Assessment

The insured reported a right-side impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Right door, Tail lamp, Left fender, Rear bumper. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 5 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 12 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 19,341.

Damage Area	Severity	Recommendation
Hood	Moderate	Repair
Tail lamp	Moderate	Replace
Right door	Minor	Repair
Rear bumper	Minor	Replace

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.