

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00022	Policy	POL-26489029
Vehicle	2023 Ford Ranger	VIN	JTBVAKV0K7PHGF7U5
Location	Ipoh	Date	2026-05-22
Weather	Cloudy	Road	Dry Asphalt

Coverage Assessment

The insured reported a right-side impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Tail lamp, Rear bumper, Left headlamp, Hood. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 6 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 25 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 24,702.

Damage Area	Severity	Recommendation
Front bumper	Moderate	Replace
Left fender	Minor	Replace
Tail lamp	Major	Repair
Hood	Minor	Repair

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.