

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00023	Policy	POL-26299466
Vehicle	2023 Toyota Corolla	VIN	JTZ2R12GDU56YV0BF
Location	Penang	Date	2026-05-01
Weather	Clear	Road	Urban Road

Coverage Assessment

The insured reported a flood exposure involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Left headlamp, Rear bumper, Left fender, Tail lamp. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 5 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 18 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 21,498.

Damage Area	Severity	Recommendation
Left headlamp	Major	Repair
Rear bumper	Minor	Replace
Tail lamp	Moderate	Inspect
Front bumper	Minor	Replace

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.