

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00026	Policy	POL-43926006
Vehicle	2022 Hyundai Tucson	VIN	JTCFL8UB7Y413YRWA
Location	Penang	Date	2026-05-01
Weather	Cloudy	Road	Dry Asphalt

Coverage Assessment

The insured reported a multiple panel damage involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Front bumper, Right door, Tail lamp, Left fender. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 5 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 18 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 27,501.

Damage Area	Severity	Recommendation
Tail lamp	Moderate	Inspect
Right door	Minor	Replace
Rear bumper	Minor	Inspect
Hood	Minor	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.