

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00027	Policy	POL-42047778
Vehicle	2020 Mercedes-Benz GLC	VIN	JTE31GME386C18YAH
Location	Ipoh	Date	2026-05-08
Weather	Cloudy	Road	Wet Asphalt

Coverage Assessment

The insured reported a front-left impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Tail lamp, Rear bumper, Right door, Front bumper. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 6 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 27 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 14,408.

Damage Area	Severity	Recommendation
Left fender	Major	Inspect
Right door	Moderate	Inspect
Tail lamp	Major	Repair
Rear bumper	Minor	Replace

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.