

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00034	Policy	POL-10711032
Vehicle	2025 BMW 320i	VIN	JTUF3VR2D3MG9HM15
Location	Johor Bahru	Date	2026-05-17
Weather	Cloudy	Road	Concrete

Coverage Assessment

The insured reported a flood exposure involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Left headlamp, Tail lamp, Rear bumper, Right door. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 7 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 26 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 14,922.

Damage Area	Severity	Recommendation
Hood	Minor	Inspect
Front bumper	Minor	Inspect
Right door	Moderate	Repair
Tail lamp	Major	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.