

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00036	Policy	POL-68121558
Vehicle	2024 Mercedes-Benz GLC	VIN	JTV19TJZ7UJSRCRT0
Location	Seremban	Date	2026-05-05
Weather	Overcast	Road	Concrete

Coverage Assessment

The insured reported a front-left impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Left fender, Left headlamp, Hood, Tail lamp. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 5 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 16 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 15,034.

Damage Area	Severity	Recommendation
Left fender	Minor	Inspect
Front bumper	Moderate	Repair
Left headlamp	Minor	Repair
Rear bumper	Major	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.