

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00046	Policy	POL-72902707
Vehicle	2023 Audi Q5	VIN	JTPPYAX2KEKM68PN1
Location	Johor Bahru	Date	2026-05-24
Weather	Rain	Road	Dry Asphalt

Coverage Assessment

The insured reported a rear-end collision involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Left fender, Hood, Tail lamp, Front bumper. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 6 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 22 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 13,388.

Damage Area	Severity	Recommendation
Hood	Moderate	Repair
Tail lamp	Major	Replace
Front bumper	Minor	Replace
Rear bumper	Major	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.