

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00047	Policy	POL-33695741
Vehicle	2020 Mercedes-Benz GLC	VIN	JTDVYT8M30G68XVM8
Location	Ipoh	Date	2026-05-20
Weather	Cloudy	Road	Concrete

Coverage Assessment

The insured reported a right-side impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Right door, Front bumper, Left headlamp, Tail lamp. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 6 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 24 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 10,853.

Damage Area	Severity	Recommendation
Right door	Minor	Inspect
Tail lamp	Major	Replace
Left fender	Moderate	Repair
Left headlamp	Moderate	Repair

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.