

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00003	Policy	POL-50651598
Vehicle	2020 BMW 320i	VIN	JTB12NZAA8R72F1PY
Location	Seremban	Date	2026-05-14
Weather	Overcast	Road	Urban Road

Coverage Assessment

The insured reported a flood exposure involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Left fender, Tail lamp, Rear bumper, Front bumper. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 7 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 23 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 19,940.

Damage Area	Severity	Recommendation
Left headlamp	Moderate	Replace
Right door	Minor	Repair
Left fender	Moderate	Repair
Rear bumper	Major	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.