

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00004	Policy	POL-98543324
Vehicle	2022 Audi Q5	VIN	JTD2SHCFB36ULA65M
Location	Johor Bahru	Date	2026-05-23
Weather	Clear	Road	Urban Road

Coverage Assessment

The insured reported a right-side impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Hood, Front bumper, Right door, Left fender. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 5 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 13 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 21,387.

Damage Area	Severity	Recommendation
Right door	Minor	Replace
Rear bumper	Minor	Repair
Left headlamp	Moderate	Replace
Hood	Major	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.