

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00005	Policy	POL-36391269
Vehicle	2021 Hyundai Tucson	VIN	JTD1R62S13DWZS51W
Location	Ipoh	Date	2026-05-20
Weather	Rain	Road	Urban Road

Coverage Assessment

The insured reported a flood exposure involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Hood, Tail lamp, Right door, Left fender. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 6 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 13 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 26,406.

Damage Area	Severity	Recommendation
Tail lamp	Minor	Repair
Rear bumper	Minor	Inspect
Left fender	Moderate	Replace
Front bumper	Minor	Repair

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.