

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00007	Policy	POL-45508604
Vehicle	2020 Honda Civic	VIN	JTEYJFS31LJSZDKLF
Location	Ipoh	Date	2026-05-15
Weather	Cloudy	Road	Concrete

Coverage Assessment

The insured reported a multiple panel damage involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Rear bumper, Tail lamp, Left fender, Right door. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 4 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 20 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 19,527.

Damage Area	Severity	Recommendation
Hood	Major	Inspect
Tail lamp	Minor	Repair
Rear bumper	Major	Repair
Left headlamp	Major	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.