

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00008	Policy	POL-41968116
Vehicle	2024 Hyundai Tucson	VIN	JT2M7605Z1KASD8BF
Location	Seremban	Date	2026-05-18
Weather	Rain	Road	Urban Road

Coverage Assessment

The insured reported a front-left impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Left fender, Tail lamp, Right door, Rear bumper. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 6 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 19 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 22,997.

Damage Area	Severity	Recommendation
Rear bumper	Major	Inspect
Left headlamp	Minor	Repair
Front bumper	Minor	Inspect
Tail lamp	Major	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.