

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00011	Policy	POL-80725829
Vehicle	2021 BMW 320i	VIN	JT8NHAY2ENKT13RDG
Location	Shah Alam	Date	2026-05-24
Weather	Overcast	Road	Dry Asphalt

Coverage Assessment

The insured reported a flood exposure involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Tail lamp, Left headlamp, Hood, Right door. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 8 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 18 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 17,277.

Damage Area	Severity	Recommendation
Left headlamp	Moderate	Repair
Front bumper	Minor	Replace
Left fender	Minor	Inspect
Right door	Minor	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.