

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00013	Policy	POL-41232239
Vehicle	2023 Mercedes-Benz GLC	VIN	JTVCKWRFCH32CRA7P
Location	Kuala Lumpur	Date	2026-05-16
Weather	Cloudy	Road	Dry Asphalt

Coverage Assessment

The insured reported a front-left impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Rear bumper, Tail lamp, Left fender, Front bumper. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 4 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 17 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 7,247.

Damage Area	Severity	Recommendation
Front bumper	Minor	Repair
Tail lamp	Minor	Replace
Left fender	Major	Repair
Right door	Moderate	Repair

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.