

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00024	Policy	POL-63278545
Vehicle	2020 BMW 320i	VIN	JTNWBGJKT2N12VC18
Location	Shah Alam	Date	2026-05-16
Weather	Clear	Road	Concrete

Coverage Assessment

The insured reported a right-side impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Left fender, Tail lamp, Right door, Hood. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 4 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 14 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 21,744.

Damage Area	Severity	Recommendation
Front bumper	Moderate	Repair
Tail lamp	Major	Inspect
Hood	Minor	Replace
Rear bumper	Major	Replace

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.