

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00031	Policy	POL-30161381
Vehicle	2025 Audi Q5	VIN	JTX84VPG9MGGT0YH4
Location	Seremban	Date	2026-05-21
Weather	Cloudy	Road	Concrete

Coverage Assessment

The insured reported a multiple panel damage involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Right door, Hood, Front bumper, Rear bumper. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 3 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 22 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 27,484.

Damage Area	Severity	Recommendation
Front bumper	Minor	Inspect
Left headlamp	Minor	Replace
Tail lamp	Moderate	Repair
Right door	Major	Replace

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.