

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00033	Policy	POL-29750391
Vehicle	2020 BMW 320i	VIN	JTHHGUB299JF7W7KE
Location	Penang	Date	2026-05-09
Weather	Overcast	Road	Urban Road

Coverage Assessment

The insured reported a rear-end collision involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Left headlamp, Front bumper, Left fender, Rear bumper. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 6 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 11 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 14,579.

Damage Area	Severity	Recommendation
Front bumper	Major	Inspect
Left headlamp	Major	Replace
Hood	Minor	Repair
Left fender	Major	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.