

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00038	Policy	POL-69412739
Vehicle	2025 BMW 320i	VIN	JT8SEJR8PF8R5Z7TK
Location	Penang	Date	2026-05-02
Weather	Rain	Road	Concrete

Coverage Assessment

The insured reported a right-side impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Right door, Front bumper, Left fender, Rear bumper. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 5 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 20 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 18,573.

Damage Area	Severity	Recommendation
Left fender	Moderate	Inspect
Front bumper	Major	Repair
Hood	Minor	Inspect
Left headlamp	Moderate	Replace

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.