

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00039	Policy	POL-92701728
Vehicle	2020 Toyota Corolla	VIN	JTE4FKTBU1PJGSAN9
Location	Seremban	Date	2026-05-02
Weather	Overcast	Road	Wet Asphalt

Coverage Assessment

The insured reported a multiple panel damage involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Rear bumper, Hood, Left headlamp, Tail lamp. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 7 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 11 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 24,135.

Damage Area	Severity	Recommendation
Hood	Minor	Replace
Front bumper	Major	Replace
Tail lamp	Minor	Inspect
Rear bumper	Moderate	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.