

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00043	Policy	POL-50996053
Vehicle	2020 Toyota Corolla	VIN	JTRJD7YKNDVXL60A5
Location	Johor Bahru	Date	2026-05-20
Weather	Cloudy	Road	Wet Asphalt

Coverage Assessment

The insured reported a flood exposure involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Right door, Rear bumper, Tail lamp, Left headlamp. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 3 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 20 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 8,429.

Damage Area	Severity	Recommendation
Hood	Minor	Inspect
Tail lamp	Moderate	Inspect
Left headlamp	Minor	Inspect
Left fender	Minor	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.