

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00048	Policy	POL-83035682
Vehicle	2022 Tesla Model 3	VIN	JTN1RMFPAMCLK44NK
Location	Johor Bahru	Date	2026-05-15
Weather	Overcast	Road	Urban Road

Coverage Assessment

The insured reported a right-side impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Left headlamp, Hood, Tail lamp, Front bumper. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 6 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 13 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 22,756.

Damage Area	Severity	Recommendation
Tail lamp	Moderate	Repair
Right door	Moderate	Inspect
Hood	Minor	Inspect
Front bumper	Major	Repair

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.