

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00049	Policy	POL-28857916
Vehicle	2025 Ford Ranger	VIN	JTAAK0HLRVNBP1ZK9
Location	Johor Bahru	Date	2026-05-25
Weather	Overcast	Road	Concrete

Coverage Assessment

The insured reported a rear-end collision involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Tail lamp, Front bumper, Right door, Left headlamp. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 7 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 14 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 4,648.

Damage Area	Severity	Recommendation
Front bumper	Minor	Inspect
Tail lamp	Moderate	Replace
Left fender	Minor	Repair
Left headlamp	Moderate	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.