

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00050	Policy	POL-74270092
Vehicle	2021 Ford Ranger	VIN	JTTF9R5H61P1G2UBD
Location	Kuala Lumpur	Date	2026-05-09
Weather	Clear	Road	Wet Asphalt

Coverage Assessment

The insured reported a right-side impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Tail lamp, Rear bumper, Left fender, Left headlamp. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 5 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 19 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 20,881.

Damage Area	Severity	Recommendation
Tail lamp	Minor	Repair
Left headlamp	Minor	Inspect
Hood	Major	Inspect
Left fender	Minor	Replace

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.