
LCD

1.Displaying time and temperature.()

Hard Ware



DHT11

.Temperature measuring and sending data to ESP32.()

lard Ware

ESP32 reads data from DHT11 via sensor pins