The Kelpie Safety Precautions

Manufacturing

- Do not touch the 3D printer nozzle when printing
- Be careful when taking off the supports from the 3D printed parts as they may be sharp

Operation

- Do not touch the servos when the robot it powered as it may get hot
- Avoid getting too close to the robot when in motion as you may get hit/pinched
- Do not use a LiPo battery when it is overcharged or undercharged

Storing

- Do not leave the LiPo battery in the robot when storing
 - o Always discharge the battery and store it in a safe location