



Heidelberg
Materials

1/7/2025

Time In:

Time Out: 6:07

Plant: U857

BOL 1725172271

THORNTON

322 S. Williams St.

THORNTON, IL 60476

INDOT 2472 MDOT 91-006 Q982104

IDOT 50312-04

Total:

Customer: 60311596 WITECH COMPANY INC

Order : 6100208257

PROJECT PRESTO - New Carlisle

31480 EDISON RD

NEW CARLISLE, IN 46552 US

P.O. : NON UNION

Product : 56001222 052CA06 GRADE 8

	UNIT	TOTALS		Pounds	Tons
Material:			Gross	73220	36.61
Freight:			Tare	27400 *	13.70 *
Tax:			Net	45820	22.91
Fee / Fuel:					
Other Chrg:	No				
				22.91	Ton
Dispatch:		916624	* P. I.		Scale:
Ordered Loads:	8				P/D Status: Deliver
Remaining Loads:	8		Reference Ticket Number:		
Today:	22.91	Loads: 1.00	Carrier : 6008967 Z FORCE TRANSPC		
			Vehicle : ZF0321		
			Z FORCE 321		
			License :		
			Trailers :		
			Weighmaster: Horwath, Jamie (Thornto		

Inv Ship To:

See terms, liability limitation and health hazard warning below

Received:

LIMITED WARRANTY AND REMEDIES

Notwithstanding any provision in any purchase order or other document of Buyer, this sale is subject to the following Limited Warranty and Remedies, which Buyer is deemed to accept and agree to by acceptance of delivery or use of goods. Heidelberg Materials warrants that at the time of delivery, the goods will conform to the applicable specifications set forth in the Quotation. Acknowledgement of Order, or other sales document signed by Heidelberg Materials for this delivery. THE FOREGOING WARRANTY IS EXCLUSIVE AND IN LIEU OF ALL OTHER WARRANTIES, WHETHER WRITTEN, ORAL OR IMPLIED, IN FACT OR IN LAW (INCLUDING IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE). If the goods do not conform to this limited warranty when delivered and Heidelberg Materials is notified within 30 days of delivery, Buyer's sole and exclusive remedy and Heidelberg Materials' sole liability, whether in contract, tort, warranty, strict liability, or any other legal theory, is for Heidelberg Materials, at its sole option, to either (i) repair or replace the non-conforming goods, FOB Heidelberg Materials plant with full freight allowed to the jobsite, or (ii) refund the price paid for the non-conforming goods. HEIDELBERG MATERIALS WILL NOT BE LIABLE FOR DELAY, SPECIAL, INCIDENTAL, OR CONSEQUENTIAL DAMAGES. Heidelberg Materials' liability, whether under contract, tort (including negligence), warranty, strict liability, or any other legal theory, shall not exceed the price of the goods or portion thereof on which such liability is based.

GHS Hazard Warnings



DANGER

May cause cancer.

May cause damage to organs (lung) through prolonged or repeated exposure.

Causes skin irritation and serious eye irritation.

PREVENTION: Obtain special instructions before use. Do not handle until all safety precautions have been read and understood.

Wash any exposed body parts after handling. Wear protective gloves, clothing, eye protection and face protection.

RESPONSE: If exposed or concerned: Get medical advice/attention. If on skin: Wash with plenty of water. Take off contaminated clothing immediately and wash it before reuse. If in eyes: Rinse continuously with water for several minutes. Remove contact lenses, if present and easy to do.

STORAGE: Restrict or control access to stockpile areas (store locked up). Engulfment hazard. To prevent burial or suffocation, do not enter a confined space, such as a silo, bulk truck or other storage container or vessel that stores or contains material without an effective procedure for ensuring safety.

DISPOSAL: Dispose of contents/container in accordance with local, regional, national, and international regulations.

SUPPLEMENTAL INFORMATION: Before handling product determine appropriate ventilation or respiratory protection. Repeated inhalation of respirable crystalline silica (quartz) may cause lung cancer. Health risk is dependent upon work duration and levels of potential silica exposure in the workplace.

WHILE IN VEHICLE: Obey speed, directional and caution signs; Give right of way to loaded mobile equipment; Stay clear of other vehicles' blind areas;

Keep safe following distance from other vehicles; Set brakes, if on grade, chock wheels; Always check overhead clearance before raising truck bed;

Never travel with truck bed raised; Never stop under a conveyor, near plant structures, or where your vehicle will restrict traffic; Leave clearance between your vehicle and others; Remain in your vehicle while being loaded for safety; Dump overloads only at specified locations. Do not park close to stockpile face.

LEAVING CAB: Wear hardhat and safety glasses; Use designated station to safely access truck bed;

Watch for moving vehicles; Never walk or stand between back of truck and stockpile.

UNSAFE CONDITIONS: Report any unsafe conditions or incidents to site management immediately.

NOTE: Your signature acknowledges receipt of these requirements and your agreement to abide by these rules.

See SDS before using this product available at www.Heidelbergmaterials.us 972-653-5500