

Topic: Compression refrigeration cycle (practical work in laboratory)

Lecture 11

Helpful Reading:

Vapour Compression Refrigeration Cycles

Ch 9: 9.8 – 9.11 Borgnakke & Sonntag Ed. 8

Ch 11: 11-1 – 11-7 Cengel and Boles Ed. 7




Lab sessions:

- Sign up if you have not already done so
- Details regarding location and remote access have been emailed for most sessions




<u>Task</u>: Ultimately we will evaluate the coefficient of performance of the refrigeration system.

COP = rate of heat flow in from the low temperature reservoir divided by the electrical power of the compressor







HAMBURG

ET 411C

COMPRESSION REFRIGERATION SYSTEM



Refrigerant Working Fluid Analysis


Process 1-2: Compression of working fluid


- Refrigerant compressed from vapour to superheated vapour
- Assumptions: steady-state device, ΔKE, ΔPE is neglected,
- Adiabatic (?)

1st Law:

$$0 = (\dot{Q}_{in} - \dot{Q}_{out}) + (\dot{W}_{in} - \dot{W}_{out}) + \dot{m}_1 h_1 - \dot{m}_2 h_2$$

$$\dot{W}_{in} = \dot{m}(h_2 - h_1) - \dot{Q}_{net}$$







Refrigerant Working Fluid Analysis


Process 2-3: Heat rejection via condensation


- · Refrigerant condenses from vapour to liquid
- Assumptions: steady-state device, ΔKE, ΔPE is neglected, neglect work

1st Law: Refrigerant is system

•
$$(\dot{Q}_{in} - \dot{Q}_{out}) + (\dot{W}_{in} - \dot{W}_{out}) + \dot{m}_2 h_2 - \dot{m}_3 h_3 = 0$$

$$\bullet \quad \dot{Q}_{H,out} = \dot{m}(h_2 - h_3)$$








Refrigerant Working Fluid Analysis

Process 3-4: throttling

- Drop in refrigerant pressure and temperature
- Assumptions: steady-state device, ΔKE, ΔPE is neglected,
- Adiabatic (?), no work

1st Law:

- $(\dot{Q}_{in} \dot{Q}_{out}) + (\dot{W}_{in} \dot{W}_{out}) + \dot{m}_3 h_3 \dot{m}_3 h_3 = 0$
- $h_3 = h_4$ if adiabatic





Refrigerant Working Fluid Analysis


Process 4-1: Heat addition, evaporation


- Refrigerant evaporates to a vapour
- Assumptions: steady-state device, ΔKE, ΔPE is neglected, neglect work

1st Law: Refrigerant is system

•
$$(\dot{Q}_{in} - \dot{Q}_{out}) + (\dot{W}_{in} - \dot{W}_{out}) + \dot{m}_4 h_4 - \dot{m}_1 h_1 = 0$$

$$\bullet \quad \dot{Q}_{L,in} = \dot{m}(h_1 - h_4)$$








Overall Lab Setup

Process 1-2: Compression $\dot{W}_{in} = \dot{m}_R (h_2 - h_1) - \dot{Q}_{loss?}$

Process 2-3: Heat rejection $\dot{Q}_H = \dot{m}_R (h_2 - h_3)$

Process 3-4: Throttling $h_3 = h_4$


Process 4-1: Heat addition $\dot{Q}_{L,in} = \dot{m}_R (h_4 - h_1)$







REAL P-v and P-h diagrams

 Notice that these diagrams might deviate from those in the book because our system can deviate from ideal (i.e. we have losses and irreversibilities not accounted for in ideal equations).






 $\dot{Q}_{H,out}$



The Remote Lab and Calculation App School of Engineering



Wed Feb-26 0900-0959

https://app.practable.io/ed0/book/?s=SwkcTz

Making measurements



ower resolution.


more accurate, precise/repeatable

 All measurement devices have potential errors associated with measuring a variable of interest

ISSUES TO CONSIDER:

- Precision: how widely spread are your measurements?
- Repeatability: do you get the same results when you do the experiment a second time?
- Accuracy: how close is the measurement to the actual value?
- Resolution: what is the smallest change that can be measured?

Unless otherwise stated assume an instrument is 100% accurate



High resolution,

inaccurate, precise/repeatable

Unstable gauges



In a real experiment, gauges fluctuate.

So... take many measurements and average.




Image by fernandozhiminaicela on Pixabay

Potential resolution error




Resolution

 Potential resolution error is typically estimated as ± ½ smallest scale division

Example

- Water flow rate (cc/min) → (cm³/min)
- Volumetric flow rate
- Smallest scale division: 0.5 cc/min
- Uncertainty: 0.25 cc/min
- Reading: 4.00 cc/min ± 0.25 cc/min



Analysing uncertainty



What is uncertainty?

- Consider some quantity Y that is to be measured
- The extracted measurement is y
- Let standard uncertainty associated with the measurement be U_{standard}(y)
- Under certain specified conditions, the probability, P, that the 'true' value of Y lies within the range $y \pm U_{standard}(y)$ is P = 68%.

Analysing uncertainty



Two categories of error: Type A and Type B

Very helpful reference:

https://physics.nist.gov/cuu/Uncertainty/index.html

Type A: 'random errors'

Type A uncertainty = standard deviation of a set of measurements

Type B: e.g. potential resolution error Statistical treatment depends on source of error

Type A uncertainties



Example (fictional) - Temperature, *T*, is measured five times:

21.3°C, 21.2°C, 21.5°C, 21.6°C, 21.0°C

$$mean = \langle x \rangle = \frac{\sum_{i}^{N} x_{i}}{N}$$

Mean = (21.3+21.2+21.5+21.6+21.0)/5 = 21.32°C

standard deviation =
$$\sigma = \sqrt{\langle x^2 \rangle - \langle x \rangle^2}$$

where $\langle x^2 \rangle = \frac{\sum_i^N x_i^2}{N}$

$$\langle x^2 \rangle = (21.3^2 + 21.2^2 + 21.5^2 + 21.6^2 + 21.0^2)/5 = 454.5880$$

$$< x >^2 = 454.5424$$

$$\sigma = \sqrt{(454.5880 - 454.5424)} = 0.2135$$
°C = uncertainty

With this uncertainty, should only quote mean to 1dp i.e. 21.3°C with uncertainty of 0.2°C. (Note: did not round until the end of the calc.)

Type B uncertainties



Example (fictional) - Temperature, *T*, is measured to be 20.1°C.

- The smallest division on the gauge is 0.1°C.
- The potential resolution error, e, is ± 0.05 °C.
- In principle, the actual temperature could be anywhere between 20.05°C and 20.15°C.
- Assume that the probability of it lying at a given point in the range is the same as the probability of it lying at any other given point in the range
- Mathematically, this distribution gives rise to a standard uncertainty of $\frac{e}{\sqrt{3}}$

Combining uncertainties

Two scenarios

- To obtain the value of interest, it was necessary to combine two
 other values that each had associated uncertainties
- Two or more different kinds of uncertainty contribute to the overall uncertainty for a given value

Combining uncertainties

Scenario 1

To obtain the value of interest (y), it was necessary to combine two or more other values (x_i) that each had associated uncertainties.

(a)
$$y = a_1x_1 + a_2x_2 + a_3x_3 + ... + a_ix_i$$

Rule 1a: The uncertainty in y is u_c , where

$$u_c^2 = a_1^2 u_{x,1}^2 + a_2^2 u_{x,2}^2 + a_3^2 u_{x,3}^2 + \dots + a_j^2 u_{x,j}^2$$

 $u_{x,1}$ is the uncertainty in x_1 .

(b)
$$y = A x_1^a x_2^b x_3^c \dots x_j^p$$

Rule 1b:

$$\left(\frac{u_c}{|y|}\right)^2 = a^2 \left(\frac{u_{x,1}}{|x_1|}\right)^2 + b^2 \left(\frac{u_{x,2}}{|x_2|}\right)^2 + c^2 \left(\frac{u_{x,3}}{|x_3|}\right)^2 + \dots + p^2 \left(\frac{u_{x,j}}{|x_j|}\right)^2$$

Combining uncertainties



Scenario 2 - Two or more different kinds of uncertainty (u_i) contribute to the overall uncertainty (u) for a given value.

Rule 2: Sum errors in quadrature i.e. $u^2 = \sum_{i=1}^{N} u_i^2$

Example:

- I have extracted a value, y, by taking the mean of a set of N
 measurements.
- Two sources of uncertainty: random error and 'potential resolution error'
- The standard deviation of the measurements is σ , so $u_1 = \sigma$
- The potential measurement error for each measurement is e
- The uncertainty associated with that is $e/(\sqrt{3})$
- Calculating the mean involved adding up all the individual measurements and dividing by N
- Applying rule 1a from previous slide, $u_2 = e/\sqrt{(3N)}$
- Need to apply **rule 2** to combine u_1 and u_2

$$u^2 = \sigma^2 + \frac{e^2}{3N}$$



It is possible to derive all three rules from first principles

but we are not going to do this today.


See here for more info on

the law of propagation of uncertainty:

https://physics.nist.gov/cuu/Uncertainty/combination.html

Measurement Uncertainty





- Enthalpies are dependent on temperature (less on pressure)
- How do we find the uncertainties of enthalpies
- Find sensitivity of enthalpy for range of temperatures you measure