LS-DYNA Crash Tutorial 1 Page 1 of 13

PRE AND POST-PROCESS CASE STUDY

SIMPLE CRASH TEST PRE AND POST-PROCESSING

The objective of this case study is to pre and post-processing a simple LS-DYNA Crash test. The analysis is carried out in nine steps:

- GiD-LSDYNA installation
- General data definition
- Part definition
- · Constraints definition
- Initial conditions definition
- Postprocessing options selection
- Model Meshing
- Simulation run
- Results viewing




Figure 1. Problem overview

LS-DYNA Crash Tutorial 1 Page 2 of 13

1. GID-LSDYNA INSTALLATION

At the moment, GiD-LSDYNA interface is only available in Windows OS. Follow these instructions to install it:

- 1. Install GiD Software on your computer
- 2. Run GiD software (from your program menu or from the created desktop icon).
- 3. Enter your license key or select it from a specific path (only if license alert appears)
- Install Isdyna interface from Internet Retrieve section (Data menu). Lsdyna will be ticked in available problemtypes list (Data->Problem type of GiD menu). If not, please select it.
- 5. By default, the interface menu (a data tree showing created groups and problem data) should appear on the left of your screen. If you can't see it, please click (**Data->Data(internal)** of GiD menu).

2. GENERAL DATA DEFINITION

You can also find the model of this case in the Internet Retrieve section. It should be installed in your GiD Examples folder (for instance C:/Program Files/GiD/Gid Isdyna 1.1b/Examples). The model is named *gid_Isdyna_tutorial.gid*.


- 1. Open our case. **Files->Open** of GiD menu and select *gid_lsdyna_tutorial.gid* path
- Choose Render→Flat from the mouse menu if this option is not selected (right click on screen)
- Choose Rotate→Trackball from the mouse menu (this tool is also available by pressing ALT key+ left click). Make a few changes to the perspective in order to get an idea of the geometry under study
- 4. Edit **General Data** information in the interface menu:
 - 1. In **Units** menu, set **Mesh Units** to cm (to represent human being sizes)
 - 2. In **Gravity** menu, activate gravity and set its value to 9,81 m/s² (in X+ sense)

LS-DYNA Crash Tutorial 1 Page 3 of 13

3. In Solver menu, set End time to 0.01 s

3. PART DEFINITION

- 1. GiD-LSDYNA Interface is based in *group* concept. A *group* is a group of geometrical entities or mesh elements where one or several conditions are applied. These conditions could define geometrical properties and materials, loads, constraints, etc. Property groups are very important in this case, because in LS-DYNA every element must be related with a material (it means that in our interface each geometrical entity should be related with a single property group).
- Most of problem parts are already defined as groups. You can notice it by drawing shell parts. Please right click **Properties->Shells** in the interface menu. Select **Draw-Groups** option.
- 3. First we must define materials. By default, one material sample of each type has been created. More materials could be created (right click in a material type) and modified with the interface (Figure 2).



LS-DYNA Crash Tutorial 1 Page 4 of 13

To modify material properties user just have to double click material's name and edit each field like another interface group. In this case we will use *Elastic1* and *Rigid1* materials, but we don't need to modify its properties (we will use default values).

- 4. To define Lower Support shell:
 - 1. Double Click in Shells->Isotropic Shell
 - 2. Set Thickness to 0.01 m
 - 3. Select **Elastic1** Material in material drop box
 - 4. Click in Group command (icon placed next to drop list) and select Lower support surface form the screen (Figure 3). Press ESC after selection.
 - 5. Change group name to *Lower Support* (optional)
 - 6. Click OK to create this part
- 3. To define Right foot:
 - 1. Double Click in Shells->Isotropic Shell
 - 2. Set Thickness to 0.01 m
 - 3. Select **Rigid1** Material in material drop box
 - 4. Click in Group command (icon placed next to drop list) and select Right Foot surface form the screen (Figure 3), if render problems appears please rotate the model to solve them. Press ESC after selection.
 - 5. Change group name to *Right Foot* (optional)
 - 6. Click OK to create this part

LS-DYNA Crash Tutorial 1 Page 5 of 13




Figure 3.Model parts

4. CONSTRAINTS DEFINITION

- 1. To represent the crash seat will suffer an important deceleration. To apply this constraint please follow these steps:
 - 1. Double Click in Constraints->Fixed Constraints
 - 2. In *Fixation* Flap, only tick **Z Constraint** option (acceleration will be prescribed in Z global axes direction)
 - 3. Select Acceleration flap (left click)
 - 4. Click to edit the acceleration behavior
 - 1. Tick Function of time
 - 2. From the drop list, select Interpolation *function at t*
 - 3. In data entry options, verify that *t units* are set to s

4. Choose *linear ramp* to edit four different ramps with the parameters below (click *Add at the end* after each curve data introduction):

Curve 1:

- *t_o:* 0
- t_{end}: 0.001
- Factor₀: 0
- Factor_{end}: 0
- Δt: 0.0001

Curve 2:

- *t*₀: 0.002
- t_{end}: 0.004
- Factor₀: 0
- Factor_{end}: 1
- Δt: 0.0001

Curve 3:

- t₀: 0.0045
- t_{end}: 0.006
- Factor₀: 1
- Factor_{end}: 0
- *Δt*: 0.0001

LS-DYNA Crash Tutorial 1 Page 7 of 13

Curve 4:

- *t_o*: 0.007

- t_{end}: 0.015

- Factor₀: 0

- Factor_{end}: 0

- *∆t:* 0.002

- 5. Click *Ok* to close function editor
- 5. Set az value to -15000 m/s². This factor will multiply the defined curve
- 6. Select surface icon \$\square\$ from the available entities.
- 7. Click group command and select Seat surfaces (Figure 4). Press ESC after selection




Figure 4. Seat surfaces selection

8. Name this group SeatBelt acceleration (optional)

LS-DYNA Crash Tutorial 1 Page 8 of 13

9. To include seatbealt to this prescribed motion, please go to **Data->Groups** in GiD menu and select the group created in the last step from the list. Click Send entities to group to add seatbelt fixation lines (Figure 5). Press ESC after selection. Click finish and close groups editor.



Figure 5. Seat lines selection

- 2. Most part of contacts are already defined. The interface supports several single and master slave contacts, but in this case only *Surface to Surface* contact type is applied. To prescribe contact between Trunk and the Seat belt (brest) please follow next instructions:
 - In Constraints->Contacts->Control set orientation to Part and segment input
 - 2. Double click Constraints->Contacts->Master Slave
 - 3. Select \$\square\$ from the available geometry entities
 - 4. In *Slave*, select Seat belt brest surface with the group edition command (Figure 6)
 - 5. In *Master*, select Trunk surface with the group edition command (Figure 6)

LS-DYNA Crash Tutorial 1 Page 9 of 13




Figure 6. Involved surfaces in contact definition

- 6. Click OK to finish contact definition
- 3. Most part of joints are already defined. With GiD-LSDYNA interface user can create spherical, revolute and translational joints, and define stiffness parameters. To define the joint between neck and trunk:
 - 1. Double Click in Constraints->Joints
 - 2. Set Relative Penalty to 0.0 and Joint Type to Spherical
 - 3. In *Point 1* Flap, introduce P1 x= 54 m, P1 y=0, P2 z=0.2 m. Points can also be selected from the screen with:
 - 4. Click *Draw Joint Points* button (placed under point coordinate labels) to draw entered point (after group creation, please press ESC on the screen to stop joint points viewing)
 - 4. Select 7 from the available geometry entities
 - 5. In First Entity, select Neck from the drop list
 - 6. In Second Entity, select Trunk from the drop list

LS-DYNA Crash Tutorial 1 Page 10 of 13

5. INITIAL CONDITIONS DEFINITION

In **Initial Conditions->All**, set velocity z to 56 m/s (this initial velocity will affect all nodes)

6. POSTPROCESSING OPTIONS

- 1. Double click in **Post Process** to edit GiD postprocessing options
- 2. Set interval to 0.001 s (at the bottom of the window)
- 3. Tick Write displacements, Write velocities and Write accelerations (Nodal)
- 4. Tick Write shell stresses and Write shell strains (Shells)

7. MODEL MESHING

There many meshing options implemented in GiD software. However, in this tutorial mesh creation have been simplified as much as possible. If you want to take contact with GiD meshing capabilities please visit GiD tutorials (http://gid.cimne.upc.es/support_team/su05.html).

- 1. Choose **Render->Normal** from the mouse menu (right click)
- 2. From GiD Menu, select **Mesh->Structured->Surfaces->Assign** and select seat surfaces (Figure 4). Press ESC to finish.
- 3. Set 15 as number of cells to assign to surfaces and select seat lines in Y direction (lines will be in red). Press ESC to finish.
- 4. Set 10 as number of cells to assign to surfaces and select seat lines in Z direction. Press ESC to finish.
- 5. Set 20 as number of cells to assign to surfaces and select seat lines in X direction. Press ESC twice to finish.
- 6. Choose **Render→Flat** from the mouse menu (right click on screen)

LS-DYNA Crash Tutorial 1 Page 11 of 13

7. From GiD Menu, select **Mesh->Element type->Quadrilateral**. Select Seat surfaces. Press ESC to finish.

8. From GiD Menu, select **Mesh->Generate Mesh** and set 2 as mesh size. Mesh generation will take few minutes.

8. SIMULATION RUN

- 1. From GiD Menu, select **Calculate->Solver Path** to choose your correct solver path (it will be saved for future simulations).
- 2. To run the simulation, select Calculate->Calculate
- 3. With the button 🖁 (placed in left toolbar) user can control simulation in real time
- 4. Wait until finish message appears (Figure 7)




Figure 7. Finished simulation message

9. RESULTS VIEW

- 1. When project finishes, a window appears allowing the user to analyze simulation results (click *Postprocessing* button). Postprocessing results are also available by click in toolbar icon.
- 2. After results load, a postprocessing interface menu will appear on the left of the screen
- 3. To animate the results:

LS-DYNA Crash Tutorial 1 Page 12 of 13

- 1. Select Window->View Results from the GiD menu
- 2. In Main Mesh Flap, tick *Deformed* and select *nodal* as Analysis *type* and *Displacements* as *results* (Figure 8).
- 3. Introduce 1 in Factor Field
- 4. Click Apply and Close
- 5. Select Window->Animate... from the GiD menu
- 6. Click Play Button




Figure 8. Main result selection

4. From the postprocessing interface menu, select Analysis:**Nodal->Step:0.003->Velocities->|Velocities|** to study velocity contours at t=0.003 s (Figure 9)

LS-DYNA Crash Tutorial 1 Page 13 of 13



Figure 9. Velocity contour fill