Part 1 Symbols

```
MosTafaa@MostaFa /cygdrive/d/ff/Lab3
$ arm-none-eabi-nm.exe startup.o
00000000 t _reset
         U main
00000006 t Vector_handler

MosTafaa@MostaFa /cygdrive/d/ff/Lab3
$ arm-none-eabi-nm.exe main.o
00000000 T main
00000000 D R_ODR

MosTafaa@MostaFa /cygdrive/d/ff/Lab3
$ arm-none-eabi-nm.exe Learn-in-depth-Mostafa.elf
08000050 t _reset
08000058 T main
080000d4 D R_ODR
08000056 t Vector_handler
```

Part 2 Symbols

```
MosTafaa@MostaFa MINGW32 /d/ff/Lab3/Part2 (master)
$ arm-none-eabi-nm.exe Learn-in-depth-Mostafa.elf
080000c8 T Bus_Fault
080000b0 T H_fault_Handler
0800001c T main
080000bc T MM_Fault_Handler
080000a4 T NMI_Handler
080000e0 D R_ODR
08000098 T Reset_Handler
080000d4 T Usage_Fault_Handler
08000000 T vectors
```