



RAPPORT D'INTERVENTION

INFORMATIONS DU CLIENT & SITE

Client : DGS Africa | Contact : +221 77 123 45 67
Site : Dakar, Plateau, Rue 123

DÉTAILS DE L'INTERVENTION

Date/Heure : 25/06/2026 08:21:00 au 26/06/2026 08:22:00
Technicien(s) : Moussa Diop
Type : Plomberie | Équipement : chaise anglaise

TRAVAUX RÉALISÉS

changement de l'équipement


Diagnostic :
problème de pompe

NOTES DU TECHNICIEN

L'équipement était totalement hors service. J'ai dû réinitialiser la carte mère principale et vérifier l'alimentation. Tout semble stable maintenant.

PHOTOS D'INTERVENTION

[AVANT] -



[APRES] -

```
(venv) C:\sensante>pip freeze > requirements.txt  
  
(venv) C:\sensante>
```

RECOMMANDATIONS & REMARQUES

Recommandations :

Faire attention a l'usage

SIGNATURE DU CLIENT

A rectangular box containing a handwritten signature in black ink. The signature is stylized and appears to be a combination of letters and numbers.

Signé électroniquement le : 24/06/2026 08:24:39

DYNAMIC GLOBAL SERVICES (DGS Africa)

Dakar, Sénégal | +221 33 800 00 00 | contact@dgs-africa.com