

Incident Report INC-16 — Tube leak during operation

Plant: Shakti Petrochem Unit-2 | **Asset:** HX-102 | **Date:** 2025-12-05

Description

A shell-and-tube exchanger developed a tube-side leak.

Root Cause

Under-frequency of cleaning allowed fouling and localized corrosion.

Lessons Learned

Hold to the 6-month cleaning interval; trend outlet temperature as an early indicator.