

Incident Report INC-08 — Recurrent pump seal failure

Plant: Shakti Petrochem Unit-2 | **Asset:** P-204A | **Date:** 2025-11-03

Description

A boiler feed pump suffered repeated mechanical seal failures over two months, culminating in a forced outage.

Root Cause

Coupling misalignment left uncorrected after a prior seal replacement accelerated seal face wear.

Lessons Learned

Enforce laser shaft-alignment and a recorded post-repair vibration reading after every seal replacement. Missing post-repair verification is a leading indicator of repeat failure.