

MAINTENANCE & REPAIR REPORT

Plant Engineering Dept. · Form ME-07 Rev C

REPORT NO.
RPT-4006

FAULT PATTERN ID
FP-02

DATE OF FAILURE
05/07/2026 10:00

ASSET ID
AST-011

MODEL NO.
DAIKIN-JT160

LINKED WO
WO-24255

SYMPTOMS OBSERVED

Chiller disch temp creeping 2 wks, approach temp widened. Condenser coil choked with dust/fluff.

DIAGNOSIS / ROOT CAUSE

Packing area extraction not working, housekeeping

PARTS REPLACED

FLT-COND-JT160, COIL-CLEAN-KIT

DOWNTIME (HRS)
4.5

FAULT CATEGORY
Cooling Degradation

TECHNICIAN
A. Shirodkar

SIGNATURE

