

MAINTENANCE & REPAIR REPORT

Plant Engineering Dept. · Form ME-07 Rev C

REPORT NO.

RPT-4011

FAULT PATTERN ID

FP-03

DATE OF FAILURE

30/06/2026 06:00

ASSET ID

AST-010

MODEL NO.

KSB-ETN-100

LINKED WO

WO-24333

SYMPTOMS OBSERVED

Vib reading flat 2.9 exactly for days, pump sounds normal, Accel cable chafed thru at gland.

DIAGNOSIS / ROOT CAUSE

Cable chafe on steam line route

PARTS REPLACED

TX-VIB-100mV, CBL-M12-5M

DOWNTIME (HRS)

1.0

FAULT CATEGORY

Sensor Fault

TECHNICIAN

R. Naik

SIGNATURE

