

MAINTENANCE & REPAIR REPORT

Plant Engineering Dept. · Form ME-07 Rev C

REPORT NO.

RPT-4015

FAULT PATTERN ID

FP-03

DATE OF FAILURE

08/08/2024 05:00

ASSET ID

AST-005

MODEL NO.

ABB-M3BP-160

LINKED WO

-

SYMPTOMS OBSERVED

Vib stuck at 2.0 for a week, quality flag still GOOD. Flag logic only checks range not variance.

DIAGNOSIS / ROOT CAUSE

Sensor Stuck + monitoring flag gap

PARTS REPLACED

TX-VIB-100mV

DOWNTIME (HRS)

1.0

FAULT CATEGORY

Sensor Fault

TECHNICIAN

A. Shirodkar

SIGNATURE

