

MAINTENANCE & REPAIR REPORT

Plant Engineering Dept. · Form ME-07 Rev C

REPORT NO.

RPT-4013

FAULT PATTERN ID

FP-03

DATE OF FAILURE

23/08/2023 17:38

ASSET ID

AST-008

MODEL NO.

CG-ND132

LINKED WO

-

SYMPTOMS OBSERVED

Vib flatline zero, fan clearly running. Accel mount stud sheared, sensor hanging.

DIAGNOSIS / ROOT CAUSE

Mount stud failure - vibration fatigue

PARTS REPLACED

TX-VIB-100mV

DOWNTIME (HRS)

1.0

FAULT CATEGORY

Sensor Fault

TECHNICIAN

S. Kadam

SIGNATURE

