

Aenderungsbeschreibung/Description of Revision war kZ				Kommt vor/Frequency	
Buchst./Rev.Ltr. -.14		Aenderungs-Nr./Revision Notice No. PR044856		Bearbeitungsstatus/Lifecycle Released	
Software Reference					
BlueVision New Generation Baseline 80					
Genoline New Generation Baseline 10					
Changes from Var1 Ed 01.05 to Var1 Ed 01.07					
SCR alarms/measuring points renamed					
New alarms					
Integration of GenolineNG alarms (distinguishable by product tags "BVNG" and "GLNG" AL Analog Speed Demand HI T-Bearing Gen DE HI T-Bearing Gen NDE HI T-Air Inlet Gen HI T-Air Outlet Gen HI T-Winding L1 Gen HI T-Winding L2 Gen HI T-Winding L3 Gen HI T-Winding L4 Gen HIHI T-Bearing Gen DE HIHI T-Bearing Gen NDE HIHI T-Air Inlet Gen HIHI T-Air Outlet Gen HIHI T-Winding L1 Gen HIHI T-Winding L2 Gen					
Allgemeintoleranzen/General Tolerances ISO 2768-mK			Masse/Mass kg		Format/Size
Tolerierung/Tolerancing ISO 8015		Masse/Size ISO 14405		A4	
Ausf. u.Lieferung Tech. Characteristics		Oberflaechenangaben nach MTN5033 Surface Specification per MTN5033		Werkstoff Material	
Oberflaechenschutz Surface Protection				Halbzeug,Modell Gesenk Semifinished Product Pattern, Die	
Verwendbar f.Type Applicable to Model		Allgemeine Fertigungsvorschriften nach MMN332 Production Specification per MMN 332		Material-Nr./Material No.	
Projekt-/Auftrags-Nr. Project/Order No.				XZ00E52000011	
Ref.-Nr./ Ref. No. Type1 Var01 ED01_05	Emission ID			Benennung/ Title TB / Table	
Alle Rechte aus Schutzrechtsanmeldungen vorbehalten. Weitergabe, Vervielfältigung oder sonstige Verwertung ohne Zustimmung nicht gestattet. Zuwiderhandlungen verpflichten zum Schadensersatz. All industrial property rights reserved. Disclosure, reproduction or use for any other purpose is prohibited unless our express permission has been given. Any infringement results in liability to pay damages.		WORD	Datum/Date	Name	DOKUMENTATION ALARMBESCHREIBUNG DOCUMENTATION
		Erstell. Drawn	2018-09-10 11:57:42	schaepers	
		Bearb. Change	2019-06-28 14:13:19	schaepers	
		Norm Std.	2019-06-28 14:13:19	ihmor stef	
		Gepr. Checked	2019-06-28 14:13:19	ihmor stef	
		Zeichnungs-Nr./Drawing No. ZNG00019135			Blatt/ Sheet
		Beschreibung/Description Type1 Var01 ED01_07			1 von/of 154

Aenderungsbeschreibung/Description of Revision		Kommt vor/Frequency
war kZ		
Buchst./Rev.Ltr.	Aenderungs-Nr./Revision Notice No.	Bearbeitungsstatus/Lifecycle
-.14	PR044856	Released

HIHI T-Winding L3 Gen HIHI T-Winding L4 Gen SD T-Bearing Gen DE SD T-Bearing Gen NDE SD T-Air Inlet Gen SD T-Air Outlet Gen SD T-Winding L1 Gen SD T-Winding L2 Gen SD T-Winding L3 Gen SD T-Winding L4 Gen AL Combined Warning Gen AL Combined Failure Gen HI T-Coolant Gen Out HIHI T-Coolant Gen Out HI T-Coolant Gen In HIHI T-Coolant Gen In SD T-Coolant Gen In SD T-Coolant Gen Out AL SeaWater Leakage 1 AL SeaWater Leakage 2 AL Coolant Leakage Gen AL Controller Defect Gen AL Rectifier Defect Gen SD SeaWater Leakage 1 SD SeaWater Leakage 2 SD Coolant Leakage Gen SD Controller Defect Gen SD Rectifier Defect Gen AL Coolant Leakage LO Coolant Level Aux. SD Coolant Leakage SD Coolant Level Aux. AL Comb. Fuel Prep. AL Combined Preheater AL Comb. Fuel Water Seperator HI P-Exhaust Back HIHI P-Exhaust Back SD P-Exhaust Back AL Harbour Test Mode Active WB Analog Input AI11M (SPU) WB Analog Input AI12M (SPU) WB Analog Input AI1MR (SPU) WB Analog Input AI2M (SPU) AL Com. To IO-Extension Red Lost AL Com. To IO-Extension Lost SD Power Actual Gen AL T-Air Outlet Incorrect LOLO T-Exhaust A1 LOLO T-Exhaust A2 LOLO T-Exhaust A3 LOLO T-Exhaust A4 LOLO T-Exhaust A5 LOLO T-Exhaust A6 LOLO T-Exhaust A7 LOLO T-Exhaust A8 LOLO T-Exhaust A9 LOLO T-Exhaust A10 LOLO T-Exhaust B1 LOLO T-Exhaust B2 LOLO T-Exhaust B3 LOLO T-Exhaust B4 LOLO T-Exhaust B5 LOLO T-Exhaust B6 LOLO T-Exhaust B7 LOLO T-Exhaust B8 LOLO T-Exhaust B9	
---	--

 MTU Friedrichshafen GmbH	Zeichnungs-Nr./Drawing No. ZNG00019135	Blatt/ Sheet 2 von/of 154
---	--	--

Alle Rechte aus Schutzrechtsanmeldungen vorbehalten. Weitergabe, Vervielfältigung oder sonstige Verwertung ohne Zustimmung nicht gestattet. Zuwiderhandlungen verpflichten zum Schadensersatz.
All industrial property rights reserved. Disclosure, reproduction or use for any other purpose is prohibited unless our express permission has been given. Any infringement results in liability to pay damages.

Aenderungsbeschreibung/Description of Revision war kZ		Kommt vor/Frequency
Buchst./Rev.Ltr. -14	Aenderungs-Nr./Revision Notice No. PR044856	Bearbeitungsstatus/Lifecycle Released
LOLO T-Exhaust B10 HIHI T-Exhaust A1 HIHI T-Exhaust A2 HIHI T-Exhaust A3 HIHI T-Exhaust A4 HIHI T-Exhaust A5 HIHI T-Exhaust A6 HIHI T-Exhaust A7 HIHI T-Exhaust A8 HIHI T-Exhaust A9 HIHI T-Exhaust A10 HIHI T-Exhaust B1 HIHI T-Exhaust B2 HIHI T-Exhaust B3 HIHI T-Exhaust B4 HIHI T-Exhaust B5 HIHI T-Exhaust B6 HIHI T-Exhaust B7 HIHI T-Exhaust B8 HIHI T-Exhaust B9 HIHI T-Exhaust B10 AL Stack Overflow MCS AL Fieldborder Fail MCS AL Division Zero MCS AL IOext Bus System Error AL Coolant Leakage LT SD Coolant Leakage LT AL Oil Refill Tank Empty SD Oil Refill Tank Empty AL MCS AIGroup PAN Lost CS1 AL MCS AIGroup PAN Lost CS2 AL MCS AIGroup PAN Lost CS3 AL MCS AIGroup PAN Lost CS4 AL MCS AIGroup PAN Lost CS5 AL MCS AIGroup PAN Lost CS6 AL Emerg Disengage Expected AL Com. Lost NOx EGAT Outlet2 SD NOx EGAT Outlet 2 AL MCS Instruments Lost CS1 AL MCS Instruments Lost CS2 AL MCS Instruments Lost CS3 AL MCS Instruments Lost CS4 AL MCS Instruments Lost CS5 AL MCS Instruments Lost CS6		
 MTU Friedrichshafen GmbH		Zeichnungs-Nr./Drawing No. ZNG00019135 Blatt/ Sheet 3 von/of 154
Alle Rechte aus Schutzrechtsanmeldungen vorbehalten. Weitergabe, Vervielfältigung oder sonstige Verwertung ohne Zustimmung nicht gestattet. Zuwiderhandlungen verpflichten zum Schadensersatz. All industrial property rights reserved. Disclosure, reproduction or use for any other purpose is prohibited unless our express permission has been given. Any infringement results in liability to pay damages.		

Aenderungsbeschreibung/Description of Revision war kZ		Kommt vor/Frequency
Buchst./Rev.Ltr. -14	Aenderungs-Nr./Revision Notice No. PR044856	Bearbeitungsstatus/Lifecycle Released

Alarm Description

Product	SysID	Alarm Name	Alarm Description
BVNG/GLNG	0011.025101.215.001.2	SD P-Lube Oil SaSy	The safety system sensor signal for lube oil pressure is outside the defined sensor signal range. The safety system lube oil pressure information is not available anymore for indication or monitoring. The safety functions related to this signal are not available anymore.
BVNG/GLNG	0011.015201.215.001.2	SD T-Coolant SaSy	The safety system sensor signal for coolant temperature is outside the defined sensor signal range. The safety system coolant temperature information is not available anymore for indication or monitoring. The safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006201.215.011.2	SD T-Exhaust A1	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006201.215.021.2	SD T-Exhaust A2	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006201.215.031.2	SD T-Exhaust A3	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006201.215.041.2	SD T-Exhaust A4	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006201.215.051.2	SD T-Exhaust A5	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006201.215.061.2	SD T-Exhaust A6	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006201.215.071.2	SD T-Exhaust A7	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006201.215.081.2	SD T-Exhaust A8	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006201.215.091.2	SD T-Exhaust A9	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006201.215.101.2	SD T-Exhaust A10	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006202.215.011.2	SD T-Exhaust B1	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006202.215.021.2	SD T-Exhaust B2	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006202.215.031.2	SD T-Exhaust B3	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006202.215.041.2	SD T-Exhaust B4	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006202.215.051.2	SD T-Exhaust B5	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006202.215.061.2	SD T-Exhaust B6	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006202.215.071.2	SD T-Exhaust B7	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006202.215.081.2	SD T-Exhaust B8	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006202.215.091.2	SD T-Exhaust B9	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.006202.215.101.2	SD T-Exhaust B10	The sensor signal for the single exhaust temperature of the specified cylinder is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.

 MTU Friedrichshafen GmbH	Zeichnungs-Nr./Drawing No. ZNG00019135	Blatt/ Sheet 4 von/of 154
---	--	--

Alle Rechte aus Schutzrechtsanmeldungen vorbehalten. Weitergabe, Vervielfältigung oder sonstige Verwertung ohne Zustimmung nicht gestattet. Zuwiderhandlungen verpflichten zum Schadensersatz.
All industrial property rights reserved. Disclosure, reproduction or use for any other purpose is prohibited unless our express permission has been given. Any infringement results in liability to pay damages.

Aenderungsbeschreibung/Description of Revision war kZ		Kommt vor/Frequency
Buchst./Rev.Ltr. -14	Aenderungs-Nr./Revision Notice No. PR044856	Bearbeitungsstatus/Lifecycle Released

Product	SysID	Alarm Name	Alarm Description
BVNG	0010.040704.205.001.2	AL Startpilot Fail	The connector to the start pilot have a wire break or short circuit.
BVNG	0011.020101.105.011.2	LO P-Fuel Common Rail A SaSy	Low Limit of fuel pressure in rail A (safety system)
BVNG	0011.020101.105.021.2	LO P-Fuel Common Rail B SaSy	Low Limit of fuel pressure in rail B (safety system)
BVNG	0010.025108.105.001.2	LO P-Lube Oil Last Bearing	Low Limit of lube oil pressure last bearing
BVNG	0010.025108.105.001.2	LO P-Piston Cooling Oil	Low Limit of lube oil pressure piston cool
BVNG	0010.016102.105.001.2	LO P-Raw Water before Pump	Low Limit of raw water pressure before pump reached
BVNG	0010.010101.105.001.2	LO P-Control Air	Low Limit of control air pressure reached
BVNG	0010.025106.115.001.2	LOLO P-Lube Oil Last Bearing	Lowest Limit of lube oil pressure last bearing reached
BVNG	0010.025108.115.001.2	LOLO P-Piston Cooling Oil	Lowest Limit of lube oil pressure piston cool
BVNG	0010.025109.155.001.2	HI P-Piston Cool.Oil Filt.Diff	High Limit of fuel pressure in return path
BVNG	0010.006101.155.001.2	HI P-Exhaust back	High Limit of exhaust pressure back (turbocharger)
BVNG	0010.056001.155.051.2	HI ETC 5 Speed	Speed of engine turbo charger 5 too high (limit 1).
BVNG	0010.006101.165.001.2	HIHI P-Exhaust back	Highest Limit of exhaust pressure back (turbocharger)
BVNG	0010.056001.165.051.2	HIHI ETC 5 Overspeed	Speed of engine turbo charger 5 too high (limit 2).
BVNG	1.0021.075001.205.001.2	AL Gear SaSy Comb Alarm Red	The gearbox safty system have a common red alarm. Check for the single alarm on LOP
BVNG	1.0021.075003.205.001.2	AL Gear SaSy Comb Alarm Yellow	The gearbox safty system have a common yellow alarm. Check for the single alarm on LOP
BVNG	0010.020101.225.011.2	TD P-Fuel Common Rail A	The fuel pressure difference between the redundant common rail pressure sensors is too high on engine Bank A.
BVNG	0010.020101.225.021.2	TD P-Fuel Common Rail B	The fuel pressure difference between the redundant common rail pressure sensors is too high on engine Bank B
BVNG	1.0021.043002.205.001.2	AL Gear SaSy Shutdown Expected	A limit violation was detected by the gearbox safty system and alarmed (pre warning, yellow alarm). A worsening situation will cause an automatic security shutdown.
BVNG	1.0080.059005.205.001.2	AL Clutch interlock RCS	The clutch interlock input is active, gearbox will stay in neutral.
BVNG	1.0021.043102.205.001.2	AL Security Shutdown Gear SaSy	An security shutdown was initiated. The security shutdown was initiated by an engine- or gear safety function. This alarm is attended by a second alarm indicating which problem caused the shutdown. Most security shutdowns might be overridable by the operator on his own risk. Several shutdowns are triggered within the ECU engine monitoring system. The safety system is also able to trigger a security shutdown. Gearbox safety shutdowns are triggered by the monitoring- and safety system of the SPU.
BVNG	0070.075804.245.001.2	SE Sysbus Duplicate Node	There are two or more systembus devices (SPU and SCUs) with the same systembus node address, which is not allowed. The Communication between componentes (LOP, displays, control lever, not MTU devices) may be distrubed. ==> Check the the hex rotary encoder switches of each SPU and SCU.
BVNG	0010.006402.165.011.2	HIHI T-Exhaust after LP ETC	Highest Limit of exhaust temperature (turbocharger)

 MTU Friedrichshafen GmbH	Zeichnungs-Nr./Drawing No. ZNG00019135	Blatt/ Sheet 5 von/of 154
---	--	--

Alle Rechte aus Schutzrechtsanmeldungen vorbehalten. Weitergabe, Vervielfältigung oder sonstige Verwertung ohne Zustimmung nicht gestattet. Zuwiderhandlungen verpflichten zum Schadensersatz.
All industrial property rights reserved. Disclosure, reproduction or use for any other purpose is prohibited unless our express permission has been given. Any infringement results in liability to pay damages.

Aenderungsbeschreibung/Description of Revision war kZ		Kommt vor/Frequency
Buchst./Rev.Ltr. -14	Aenderungs-Nr./Revision Notice No. PR044856	Bearbeitungsstatus/Lifecycle Released

Product	SysID	Alarm Name	Alarm Description
BVNG	0070.075232.205.011.2	AL MCS Dim PAN Lost CS1	The communication to Dim PAN on first (#1) control stand is interrupted. Dimming from the PAN won't have a effect.
BVNG	0070.075232.205.021.2	AL MCS Dim PAN Lost CS2	The communication to Dim PAN on second (#2) control stand is interrupted. Dimming from the PAN won't have a effect.
BVNG	0070.075232.205.031.2	AL MCS Dim PAN Lost CS3	The communication to Dim PAN on third (#3) control stand is interrupted. Dimming from the PAN won't have a effect.
BVNG	0070.075232.205.041.2	AL MCS Dim PAN Lost CS4	The communication to Dim PAN on fourth (#4) control stand is interrupted. Dimming from the PAN won't have a effect.
BVNG	0070.075232.205.051.2	AL MCS Dim PAN Lost CS5	The communication to Dim PAN on fifth (#5) control stand is interrupted. Dimming from the PAN won't have a effect.
BVNG	0070.075232.205.061.2	AL MCS Dim PAN Lost CS6	The communication to Dim PAN on sixth (#6) control stand is interrupted. Dimming from the PAN won't have a effect.
BVNG/GLNG	0010.057303.205.001.2	AL ECU Defect	Fatal internal ECU failure. ECU has to be replaced
BVNG/GLNG	0011.000501.165.001.2	HIHI Engine Overspeed SaSy	An engine overspeed was detected by the safety system. This alarm will normally cause an automatic emergency stop.
BVNG/GLNG	0011.025101.105.001.2	LO P-Lube Oil SaSy	A low engine lube oil pressure was detected by the safety system. A worsening situation could trigger a safety reaction.
BVNG/GLNG	0011.025101.115.001.2	LOLO P-Lube Oil SaSy	A very low engine lube oil pressure was detected by the safety system. This alarm will normally cause an automatic security shutdown. The safety reaction is alarmed with an separate alarm.
BVNG/GLNG	0011.015201.155.001.2	HI T-Coolant SaSy	A high engine coolant temperature was detected by the safety system. A worsening situation could trigger a safety reaction.
BVNG/GLNG	0011.015201.165.001.2	HIHI T-Coolant SaSy	A very high engine coolant temperature was detected by the safety system. This alarm will normally cause an automatic safety function. The safety reaction is alarmed with an separate alarm.
BVNG/GLNG	0011.043301.255.001.2	WB SaSy Emergency Stop Output	The safety system detected an open loop of it's emergency stop output. An automatic emergency stop function is not available anymore.
BVNG/GLNG	0011.043302.265.001.2	SC SaSy Emergency Stop Output	The safety system detected a short circuit of it's emergency stop output. An automatic emergency stop function is not available anymore.
BVNG/GLNG	0010.055202.155.001.2	HI T-Bearing Mean	The average bearing temperature is too high.
BVNG/GLNG	0010.006201.155.011.2	HI T-Exhaust A1	The temperature of cylinder A1 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.006201.155.021.2	HI T-Exhaust A2	The temperature of cylinder A2 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.006201.155.031.2	HI T-Exhaust A3	The temperature of cylinder A3 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.006201.155.041.2	HI T-Exhaust A4	The temperature of cylinder A4 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.006201.155.051.2	HI T-Exhaust A5	The temperature of cylinder A5 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.006201.155.061.2	HI T-Exhaust A6	The temperature of cylinder A6 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.006201.155.071.2	HI T-Exhaust A7	The temperature of cylinder A7 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.006201.155.081.2	HI T-Exhaust A8	The temperature of cylinder A8 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.006201.155.091.2	HI T-Exhaust A9	The temperature of cylinder A9 compared to the average exhaust temperature is too high.

 MTU Friedrichshafen GmbH	Zeichnungs-Nr./Drawing No. ZNG00019135	Blatt/ Sheet 6 von/of 154
---	--	--

Alle Rechte aus Schutzrechtsanmeldungen vorbehalten. Weitergabe, Vervielfältigung oder sonstige Verwertung ohne Zustimmung nicht gestattet. Zuwiderhandlungen verpflichten zum Schadensersatz.
All industrial property rights reserved. Disclosure, reproduction or use for any other purpose is prohibited unless our express permission has been given. Any infringement results in liability to pay damages.

Aenderungsbeschreibung/Description of Revision war kZ		Kommt vor/Frequency
Buchst./Rev.Ltr. -14	Aenderungs-Nr./Revision Notice No. PR044856	Bearbeitungsstatus/Lifecycle Released

Product	SysID	Alarm Name	Alarm Description
BVNG/GLNG	0010.006201.155.101.2	HI T-Exhaust A10	The temperature of cylinder A10 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.006202.155.011.2	HI T-Exhaust B1	The temperature of cylinder B1 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.006202.155.021.2	HI T-Exhaust B2	The temperature of cylinder B2 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.006202.155.031.2	HI T-Exhaust B3	The temperature of cylinder B3 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.006202.155.041.2	HI T-Exhaust B4	The temperature of cylinder B4 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.006202.155.051.2	HI T-Exhaust B5	The temperature of cylinder B5 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.006202.155.061.2	HI T-Exhaust B6	The temperature of cylinder B6 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.006202.155.071.2	HI T-Exhaust B7	The temperature of cylinder B7 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.006202.155.081.2	HI T-Exhaust B8	The temperature of cylinder B8 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.006202.155.091.2	HI T-Exhaust B9	The temperature of cylinder B9 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.006202.155.101.2	HI T-Exhaust B10	The temperature of cylinder B10 compared to the average exhaust temperature is too high.
BVNG/GLNG	0010.055201.155.011.2	HI T-Bearing 1	The temperature of bearing 1 is too high
BVNG/GLNG	0010.055201.155.021.2	HI T-Bearing 2	The temperature of bearing 2 is too high
BVNG/GLNG	0010.055201.155.031.2	HI T-Bearing 3	The temperature of bearing 3 is too high
BVNG/GLNG	0010.055201.155.041.2	HI T-Bearing 4	The temperature of bearing 4 is too high
BVNG/GLNG	0010.055201.155.051.2	HI T-Bearing 5	The temperature of bearing 5 is too high
BVNG/GLNG	0010.055201.155.061.2	HI T-Bearing 6	The temperature of bearing 6 is too high
BVNG/GLNG	0010.055201.155.071.2	HI T-Bearing 7	The temperature of bearing 7 is too high
BVNG/GLNG	0010.055201.155.081.2	HI T-Bearing 8	The temperature of bearing 8 is too high
BVNG/GLNG	0010.055201.155.091.2	HI T-Bearing 9	The temperature of bearing 9 is too high
BVNG/GLNG	0010.055201.155.101.2	HI T-Bearing 10	The temperature of bearing 10 is too high
BVNG/GLNG	0010.055201.155.111.2	HI T-Bearing 11	The temperature of bearing 11 is too high
BVNG/GLNG	0010.055201.165.011.2	HIHI T-Bearing 1	The temperature of bearing 1 is very high. This alarm might cause an automatic safety function. The safety reaction would be alarmed with a separate alarm.
BVNG/GLNG	0010.055201.165.021.2	HIHI T-Bearing 2	The temperature of bearing 2 is very high. This alarm might cause an automatic safety function. The safety reaction would be alarmed with a separate alarm.

 MTU Friedrichshafen GmbH	Zeichnungs-Nr./Drawing No. ZNG00019135	Blatt/ Sheet 7 von/of 154
---	--	--

Alle Rechte aus Schutzrechtsanmeldungen vorbehalten. Weitergabe, Vervielfältigung oder sonstige Verwertung ohne Zustimmung nicht gestattet. Zuwiderhandlungen verpflichten zum Schadensersatz.
All industrial property rights reserved. Disclosure, reproduction or use for any other purpose is prohibited unless our express permission has been given. Any infringement results in liability to pay damages.

Aenderungsbeschreibung/Description of Revision war kZ		Kommt vor/Frequency
Buchst./Rev.Ltr. -14	Aenderungs-Nr./Revision Notice No. PR044856	Bearbeitungsstatus/Lifecycle Released

Product	SysID	Alarm Name	Alarm Description
BVNG/GLNG	0010.055201.165.031.2	HIHI T-Bearing 3	The temperature of bearing 3 is very high. This alarm might cause an automatic safety function. The safety reaction would be alarmed with a separate alarm.
BVNG/GLNG	0010.055201.165.041.2	HIHI T-Bearing 4	The temperature of bearing 4 is very high. This alarm might cause an automatic safety function. The safety reaction would be alarmed with a separate alarm.
BVNG/GLNG	0010.055201.165.051.2	HIHI T-Bearing 5	The temperature of bearing 5 is very high. This alarm might cause an automatic safety function. The safety reaction would be alarmed with a separate alarm.
BVNG/GLNG	0010.055201.165.061.2	HIHI T-Bearing 6	The temperature of bearing 6 is very high. This alarm might cause an automatic safety function. The safety reaction would be alarmed with a separate alarm.
BVNG/GLNG	0010.055201.165.071.2	HIHI T-Bearing 7	The temperature of bearing 7 is very high. This alarm might cause an automatic safety function. The safety reaction would be alarmed with a separate alarm.
BVNG/GLNG	0010.055201.165.081.2	HIHI T-Bearing 8	The temperature of bearing 8 is very high. This alarm might cause an automatic safety function. The safety reaction would be alarmed with a separate alarm.
BVNG/GLNG	0010.055201.165.091.2	HIHI T-Bearing 9	The temperature of bearing 9 is very high. This alarm might cause an automatic safety function. The safety reaction would be alarmed with a separate alarm.
BVNG/GLNG	0010.055201.165.101.2	HIHI T-Bearing 10	The temperature of bearing 10 is very high. This alarm might cause an automatic safety function. The safety reaction would be alarmed with a separate alarm.
BVNG/GLNG	0010.055201.165.111.2	HIHI T-Bearing 11	The temperature of bearing 11 is very high. This alarm might cause an automatic safety function. The safety reaction would be alarmed with a separate alarm.
BVNG/GLNG	0010.006201.105.011.2	LO T-Exhaust A1	The temperature of cylinder A1 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.006201.105.021.2	LO T-Exhaust A2	The temperature of cylinder A2 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.006201.105.031.2	LO T-Exhaust A3	The temperature of cylinder A3 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.006201.105.041.2	LO T-Exhaust A4	The temperature of cylinder A4 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.006201.105.051.2	LO T-Exhaust A5	The temperature of cylinder A5 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.006201.105.061.2	LO T-Exhaust A6	The temperature of cylinder A6 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.006201.105.071.2	LO T-Exhaust A7	The temperature of cylinder A7 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.006201.105.081.2	LO T-Exhaust A8	The temperature of cylinder A8 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.006201.105.091.2	LO T-Exhaust A9	The temperature of cylinder A9 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.006201.105.101.2	LO T-Exhaust A10	The temperature of cylinder A10 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.006202.105.011.2	LO T-Exhaust B1	The temperature of cylinder B1 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.006202.105.021.2	LO T-Exhaust B2	The temperature of cylinder B2 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.006202.105.031.2	LO T-Exhaust B3	The temperature of cylinder B3 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.006202.105.041.2	LO T-Exhaust B4	The temperature of cylinder B4 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.006202.105.051.2	LO T-Exhaust B5	The temperature of cylinder B5 compared to the average exhaust temperature is too low.

 MTU Friedrichshafen GmbH	Zeichnungs-Nr./Drawing No. ZNG00019135	Blatt/ Sheet 8 von/of 154
---	--	--

Alle Rechte aus Schutzrechtsanmeldungen vorbehalten. Weitergabe, Vervielfältigung oder sonstige Verwertung ohne Zustimmung nicht gestattet. Zuwiderhandlungen verpflichten zum Schadensersatz.
All industrial property rights reserved. Disclosure, reproduction or use for any other purpose is prohibited unless our express permission has been given. Any infringement results in liability to pay damages.

Aenderungsbeschreibung/Description of Revision war kZ		Kommt vor/Frequency
Buchst./Rev.Ltr. -14	Aenderungs-Nr./Revision Notice No. PR044856	Bearbeitungsstatus/Lifecycle Released

Product	SysID	Alarm Name	Alarm Description
BVNG/GLNG	0010.006202.105.061.2	LO T-Exhaust B6	The temperature of cylinder B6 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.006202.105.071.2	LO T-Exhaust B7	The temperature of cylinder B7 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.006202.105.081.2	LO T-Exhaust B8	The temperature of cylinder B8 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.006202.105.091.2	LO T-Exhaust B9	The temperature of cylinder B9 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.006202.105.101.2	LO T-Exhaust B10	The temperature of cylinder B10 compared to the average exhaust temperature is too low.
BVNG/GLNG	0010.016101.105.001.2	LO P-Raw Water	The raw water pressure after the pump is too low (limit 1)
BVNG/GLNG	0010.006207.205.001.2	AL Exhaust Monitoring Fail	The exhaust monitoring failed due to missing cylinder cut-out status. Can be caused by a communication loss between the ECU and the monitoring device.
BVNG/GLNG	0011.043501.205.001.2	AL Security Channel def. SaSy	A sensor of the safety system was detected "Sensor Defect". The respective safety function is not available anymore.
BVNG/GLNG	0011.015201.225.001.2	TD T-Coolant	The temperature difference between the redundant coolant temperature sensors is too high.
BVNG/GLNG	0011.025101.225.001.2	TD P-Lube Oil	The pressure difference between the redundant lube oil pressure sensors is too high.
BVNG/GLNG	0010.006206.205.001.2	AL T-Exhaust L2 above/below	One of the single exhaust temperatures is well above or below the average exhaust temperature. This might trigger a safety function. The safety reaction would be alarmed with an separate alarm.
BVNG/GLNG	0010.025601.155.011.2	HI T-Splash Oil B1	The temperature of the conrod bearing splash oil measured at position 1 at the B-side of the crank case is too high
BVNG/GLNG	0010.025601.155.021.2	HI T-Splash Oil B2	The temperature of the conrod bearing splash oil measured at position 2 at the B-side of the crank case is too high
BVNG/GLNG	0010.025601.155.031.2	HI T-Splash Oil B3	The temperature of the conrod bearing splash oil measured at position 3 at the B-side of the crank case is too high
BVNG/GLNG	0010.025601.155.041.2	HI T-Splash Oil B4	The temperature of the conrod bearing splash oil measured at position 4 at the B-side of the crank case is too high
BVNG/GLNG	0010.025601.155.051.2	HI T-Splash Oil B5	The temperature of the conrod bearing splash oil measured at position 5 at the B-side of the crank case is too high
BVNG/GLNG	0010.025601.155.061.2	HI T-Splash Oil B6	The temperature of the conrod bearing splash oil measured at position 6 at the B-side of the crank case is too high
BVNG/GLNG	0010.025601.155.071.2	HI T-Splash Oil B7	The temperature of the conrod bearing splash oil measured at position 7 at the B-side of the crank case is too high
BVNG/GLNG	0010.025601.155.081.2	HI T-Splash Oil B8	The temperature of the conrod bearing splash oil measured at position 8 at the B-side of the crank case is too high
BVNG/GLNG	0010.025601.155.091.2	HI T-Splash Oil B9	The temperature of the conrod bearing splash oil measured at position 9 at the B-side of the crank case is too high
BVNG/GLNG	0010.025601.155.101.2	HI T-Splash Oil B10	The temperature of the conrod bearing splash oil measured at position 10 at the B-side of the crank case is too high
BVNG/GLNG	0010.025601.165.011.2	HIHI T-Splash Oil B1	The temperature of the conrod bearing splash oil measured at position 1 at the B-side of the crank case is very high
BVNG/GLNG	0010.025601.165.021.2	HIHI T-Splash Oil B2	The temperature of the conrod bearing splash oil measured at position 2 at the B-side of the crank case is very high
BVNG/GLNG	0010.025601.165.031.2	HIHI T-Splash Oil B3	The temperature of the conrod bearing splash oil measured at position 3 at the B-side of the crank case is very high

 MTU Friedrichshafen GmbH	Zeichnungs-Nr./Drawing No. ZNG00019135	Blatt/ Sheet 9 von/of 154
---	--	--

Alle Rechte aus Schutzrechtsanmeldungen vorbehalten. Weitergabe, Vervielfältigung oder sonstige Verwertung ohne Zustimmung nicht gestattet. Zuwiderhandlungen verpflichten zum Schadensersatz.
All industrial property rights reserved. Disclosure, reproduction or use for any other purpose is prohibited unless our express permission has been given. Any infringement results in liability to pay damages.

Aenderungsbeschreibung/Description of Revision war kZ		Kommt vor/Frequency
Buchst./Rev.Ltr. -14	Aenderungs-Nr./Revision Notice No. PR044856	Bearbeitungsstatus/Lifecycle Released

Product	SysID	Alarm Name	Alarm Description
BVNG/GLNG	0010.025601.165.041.2	HIHI T-Splash Oil B4	The temperature of the conrod bearing splash oil measured at position 4 at the B-side of the crank case is very high
BVNG/GLNG	0010.025601.165.051.2	HIHI T-Splash Oil B5	The temperature of the conrod bearing splash oil measured at position 5 at the B-side of the crank case is very high
BVNG/GLNG	0010.025601.165.061.2	HIHI T-Splash Oil B6	The temperature of the conrod bearing splash oil measured at position 6 at the B-side of the crank case is very high
BVNG/GLNG	0010.025601.165.071.2	HIHI T-Splash Oil B7	The temperature of the conrod bearing splash oil measured at position 7 at the B-side of the crank case is very high
BVNG/GLNG	0010.025601.165.081.2	HIHI T-Splash Oil B8	The temperature of the conrod bearing splash oil measured at position 8 at the B-side of the crank case is very high
BVNG/GLNG	0010.025601.165.091.2	HIHI T-Splash Oil B9	The temperature of the conrod bearing splash oil measured at position 9 at the B-side of the crank case is very high
BVNG/GLNG	0010.025601.165.101.2	HIHI T-Splash Oil B10	The temperature of the conrod bearing splash oil measured at position 10 at the B-side of the crank case is very high
BVNG/GLNG	0010.025604.205.011.2	AL Splash Oil Cal not Poss	The internal splash oil temperature calibration process was not successful.
BVNG/GLNG	0010.055201.215.011.2	SD T-Bearing 1	The temperature sensor signal for the specified bearing is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.055201.215.021.2	SD T-Bearing 2	The temperature sensor signal for the specified bearing is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.055201.215.031.2	SD T-Bearing 3	The temperature sensor signal for the specified bearing is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.055201.215.041.2	SD T-Bearing 4	The temperature sensor signal for the specified bearing is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.055201.215.051.2	SD T-Bearing 5	The temperature sensor signal for the specified bearing is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.055201.215.061.2	SD T-Bearing 6	The temperature sensor signal for the specified bearing is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.055201.215.071.2	SD T-Bearing 7	The temperature sensor signal for the specified bearing is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.055201.215.081.2	SD T-Bearing 8	The temperature sensor signal for the specified bearing is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.055201.215.091.2	SD T-Bearing 9	The temperature sensor signal for the specified bearing is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.055201.215.101.2	SD T-Bearing 10	The temperature sensor signal for the specified bearing is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.055201.215.111.2	SD T-Bearing 11	The temperature sensor signal for the specified bearing is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured safety functions related to this signal are not available anymore.
BVNG/GLNG	0010.016101.215.001.2	SD P-Raw Water	The pressure sensor signal for the raw water pressure monitoring is outside the defined sensor signal range. This measuring point is not available anymore for indication or monitoring. Configured (safety) functions related to this signal are not available anymore.
BVNG/GLNG	0010.025601.215.011.2	SD T-Splash Oil B1	The signal of the sensor measuring the temperature of the conrod bearing splash oil at position 1 at the B-side of the crank case is out of the plausible range and detected as defective.
BVNG/GLNG	0010.025601.215.021.2	SD T-Splash Oil B2	The signal of the sensor measuring the temperature of the conrod bearing splash oil at position 2 at the B-side of the crank case is out of the plausible range and detected as defective.
BVNG/GLNG	0010.025601.215.031.2	SD T-Splash Oil B3	The signal of the sensor measuring the temperature of the conrod bearing splash oil at position 3 at the B-side of the crank case is out of the plausible range and detected as defective.
BVNG/GLNG	0010.025601.215.041.2	SD T-Splash Oil B4	The signal of the sensor measuring the temperature of the conrod bearing splash oil at position 4 at the B-side of the crank case is out of the plausible range and detected as defective.

 MTU Friedrichshafen GmbH	Zeichnungs-Nr./Drawing No. ZNG00019135	Blatt/ Sheet 10 von/of 154
---	--	---

Alle Rechte aus Schutzrechtsanmeldungen vorbehalten. Weitergabe, Vervielfältigung oder sonstige Verwertung ohne Zustimmung nicht gestattet. Zuwiderhandlungen verpflichten zum Schadensersatz.
All industrial property rights reserved. Disclosure, reproduction or use for any other purpose is prohibited unless our express permission has been given. Any infringement results in liability to pay damages.