Panel No Plane No Cleaned/ DMB Id Air test PFN **Blocked** Missing wires Missing wires Prepped straws confirmed epoxy / 1 # 94 ear flooded Repairs DMB connector holes deared. pig tail on straw 79 calside (removed) straw 94 sparks @ 1.3 kV pre assy HV · gas leak test issues pass v 1 straws 27, 30, 55, 63, 83 draw high aments #67 -> got drilled on AV- side (01/08/25) Notes · Le epoched stemd off/threads 1990 /= OK epoxyin omoconn -- cleured · Air tested under DMB + 5 mil Kapton check - ok · Air tested for blocked straws - V 1

MN091 (01/09/2025) High convent wives: 27, 31, 55, 63,87 Kapten dots: 18, 19, 42, 43 [Kapton washers every where else Epoxy blocked straw: #(94) Toip issue! (79) Cess Gaine HVV