Pre Plane Assembly Summary

Panel No	Plane No	Cleaned/ Prepped	Blocked straws	Missing wires	Missing wires confirmed	PFN & stnd. off epoxy	Ear install	Ear leak test	Prep Finished	Pre
mn 150	9.	· V		100 mm m m m m m m m m m m m m m m m m m) /	Brey r Clean v	9	/	1
Repairs	0501	11 12 80	ar flood	ed		asukuniamannununununununununun	ataanaanaanaanaanaanaanaanaanaanaanaanaa	nisilaanan maanan m		777
à						9				avenosova savenosova savenosova savenosova savenosova savenosova savenosova savenosova savenosova savenosova s
	- Cap	was se	paruted to	rom PFN	, but was epo	exied back i	in plac	e with		000000000000000000000000000000000000000
	am	old-relea	sed scren	scru	wremoved 1:	2/8/21 wn				AND THE PARTY OF T
•	filled epoxy goys - left side									
HV	Ornega piece on channel 77 is not making contact?									
issues	30 Sept., 2024									
	Kapton dots: 4, 10, 11, 20, 21, 24, 25, 78, 79, 80, 81, 92, 93, 94,95									
	spartaing wire: (5)									
	HV test / fe 55 test / Gain test /									
Notes	Small epoxy gapo-left side									
										and the second s
										agent to assert the second
0	#3 p	for wi	LYOCLS	the re	stok-f	ixed				
	anaununununununununununununun			f	паштапазатинашина принастинацию	austriani mananananananananananananananananananan	ener econolic consiste consist			