Pre Plane Assembly Summary

Panel No	Plane No	Cleaned/ Prepped	Blocked straws	Missing wires	Missing wires confirmed	PFN & stnd. off epoxy	Ear install	Ear leak test	Prep Finished	Pre-assy gas leak test
mn133	9	✓				Standoffs epoxied ✓	grey ✓ clear ✓	✓	✓	✓
Repairs	ear flooded PFN cleaned DMB holes cleaned									
HV issues	All good! Except chan 20 (wires 40, 41) has a constant current of ~80 nA. Oct. 11, 2024, kapton dots: 6, 7, 54, 55, 80, 81, 82, 83, 88, 89 no hv on calside: 19 (wiggling anode on hv side)					Passed QC test	Fe55 ✓ Gain ✓ HV ✓			
Notes	epoxy in DMB connectors - cleared Left side Inner Ring is shifted outward - cover screws don't center along with all the rest (outer ring + sides) After centering 1st w/6 cover screws insert "real" stay bolts / center + insert the rest of the cover screws (+ snug up) - check Alignment that no screw edges touches the counter bore wall, snug, Replace w/shouldered stay bolts + make sure they seat well Pfn ✓ = #8 - left side									