Panel No Plane No Cleaned/ Air test la install Blocked Missing wires Missing wires PFN Prepped straws confirmed epoxy pass Leak kst. ·715 car Shooked 4,5 LHS due to epoxy leakage and 22 Repairs complete channed 4.5, 22,29 - couldn't chan Pins 0,24 - sparking wires. Cramp placed at 2-26 causes short even if - gainfield and philip disconnected - may have prinched through socket. + whe as high Re ejoxied 3 tend off Homeads : Missing onega #6/7 Left side cumont + wife 22 spanh +no possactost Rt end measurement 110.33 / left -110.20

MNO77 + Aften 1 st repairs when 7 spanh · wire 15 missing · wishe 19 amode pin missing · wire 29 high current . panattert